

5005380A

Multi Band | Ceiling Mount Omni | (2x) Linear | 360° | 3.0-5.0 dBi | MIMO

- Wideband ceiling mount omni antenna covering 698-4000 MHz
- Compact, lightweight and easy to install
- Passive intermodulation < -150 dBc @ 2x2W
- Low return loss with stable performance

Low return loss with stable performance						
Ordering Options	Model Number					
Antenna with N-Type Connector	5005380A					
Antenna with 4.3/10 Connector	5005380A-4310					
Antenna with 7/16-DIN Connector	5005380A-DIN					
Electrical Characteristics	698-4000 MHz					
Frequency Band	698-806 MHz	806-960 MHz	1710-2700 MHz	3400-4000 MHz	698-960 1710-4000	698-960 1710-4000
Polarisation	(2x) Linear					
Horizontal Beamwidth	360°				♥ Port 1	♥ Port 2
Vertical Beamwidth	90°	85°	45°	35°		
Gain	3.0 ± 0.5 dBi	3.5 ± 0.5 dBi	4.5 ± 1.0 dBi	5.0 ± 1.0 dBi		
Impedance	50Ω				iBwave	
VSWR	≤ 2.0	≤ 2.0	≤ 2.0	≤ 2.0	iBwave In-B	is available in the wilding Network ts Database -
Isolation	> 17 dB	> 17 dB	> 20 dB	> 25 dB		ecomponents.com
IM3 (2x2W)	≤ -150 dBc					
Maximum Power	50 Watts					
Connector	2 Ports, N-Type Female or 4.3-10 Female or 7/16-DIN Female					
Mechanical Characteristics						
Dimensions	Ø218 x 40 mm			Ø8.6 x 1.6 in		
Weight		0.5 kg		1.1 lbs		
Operating Temperature	-55° to +60° C -67° to +140° F					
Operational Humidity	< 95%					
Radome	ABS, White RAL9003					
Mounting Options						
Mount	Ceiling, via hole (standard)					

Quoted performance parameters are provided to offer typical or range values only and may vary as a result of normal manufacturing and operational conditions. Extreme operational conditions and/or stress on structural supports is beyond our control. Such conditions may result in damage to this product. Improvements to product may be made without notice.



5005380A

Multi Band | Ceiling Mount Omni | (2x) Linear | 360° | 3.0-5.0 dBi | MIMO



Quoted performance parameters are provided to offer typical or range values only and may vary as a result of normal manufacturing and operational conditions. Extreme operational conditions and/or stress on structural supports is beyond our control. Such conditions may result in damage to this product. Improvements to product may be made without notice.