





2U3MX065X06Fxys0 Patterns
25October2018



2U3MX065X06F20S0 Y1, $\pm$ Ports 1695-1880MHz





2U3MX065X06F20S0 Y2, ±Ports 1695-1880MHz





2U3MX065X06F60S0 Y1, $\pm$ Ports 1695-1880MHz





2U3MX065X06F60S0 Y2, ±Ports 1695-1880MHz





2U3MX065X06F100S0 Y1, $\pm$ Ports 1695-1880MHz





2U3MX065X06F100S0 Y2, ±Ports 1695-1880MHz





2U3MX065X06F20S0 Y1, ±Ports 1850-1990MHz





2U3MX065X06F20S0 Y2, $\pm$ Ports 1850-1990MHz





2U3MX065X06F60S0 Y1, ±Ports 1850-1990MHz





2U3MX065X06F60S0 Y2, ±Ports 1850-1990MHz





2U3MX065X06F100S0 Y1, $\pm$ Ports 1850-1990MHz





2U3MX065X06F100S0 Y2, $\pm$ Ports 1850-1990MHz





2U3MX065X06F20S0 Y1, ±Ports 1920-2200MHz





2U3MX065X06F20S0 Y2, ±Ports 1920-2200MHz





2C2U3MT360X06F06S0 Y1, ±Ports 1920-2200MHz





2C2U3MT360X06F06S0 Y2, ±Ports 1920-2200MHz





2U3MX065X06F100S0 Y1, ±Ports 1920-2200MHz





2U3MX065X06F100S0 Y2, $\pm$ Ports 1920-2200MHz





2U3MX065X06F20S0 Y1, ±Ports 2300-2700MHz





2U3MX065X06F20S0 Y2, ±Ports 2300-2700MHz





2U3MX065X06F60S0 Y1, $\pm$ Ports 2300-2700MHz





2U3MX065X06F60S0 Y2, ±Ports 2300-2700MHz





2U3MX065X06F100S0 Y1, $\pm$ Ports 2300-2700MHz





2U3MX065X06F100S0 Y2, ±Ports 2300-2700MHz



2U3MX065X06F00S0 P1, $\pm$ Ports 3550-3700MHz



2U3MX065X06F00S0 P2, ±Ports 3550-3700MHz



2U3MX065X06F00S0 O1, $\pm$ Ports 5150-5925MHz

