





2C2U3MT360X06Fxys0 Patterns
25October2018



2C2U3MT360X06F00S0 R1, ± Ports 696-806 MHz





2C2U3MT360X06F00S0 R1, ± Ports 806-960 MHz





2C2U3MT360X06F00S0 R2, ± Ports 696-806 MHz





2C2U3MT360X06F00S0 R2, ± Ports 806-960 MHz





2C2U3MT360X06F00S0 Y1, ±Ports 1695-1880MHz





2C2U3MT360X06F00S0 Y2, ±Ports 1695-1880MHz





2C2U3MT360X06F02S0 Y1, ±Ports 1695-1880MHz





2C2U3MT360X06F02S0 Y2, ±Ports 1695-1880MHz





2C2U3MT360X06F04S0 Y1, ±Ports 1695-1880MHz





2C2U3MT360X06F04S0 Y2, ±Ports 1695-1880MHz





2C2U3MT360X06F06S0 Y1, ±Ports 1695-1880MHz





2C2U3MT360X06F06S0 Y2, ±Ports 1695-1880MHz





2C2U3MT360X06F00S0 Y1, ±Ports 1850-1990MHz





2C2U3MT360X06F00S0 Y2, ±Ports 1850-1990MHz





2C2U3MT360X06F02S0 Y1, ±Ports 1850-1990MHz





2C2U3MT360X06F02S0 Y2, ±Ports 1850-1990MHz





2C2U3MT360X06F04S0 Y1, ±Ports 1850-1990MHz





2C2U3MT360X06F04S0 Y2, ±Ports 1850-1990MHz





2C2U3MT360X06F06S0 Y1, ±Ports 1850-1990MHz





2C2U3MT360X06F06S0 Y2, ±Ports 1850-1990MHz





2C2U3MT360X06F00S0 Y1, ±Ports 1920-2200MHz





2C2U3MT360X06F00S0 Y2, ±Ports 1920-2200MHz





2C2U3MT360X06F02S0 Y1, ±Ports 1920-2200MHz





2C2U3MT360X06F02S0 Y2, ±Ports 1920-2200MHz





2C2U3MT360X06F04S0 Y1, ±Ports 1920-2200MHz





2C2U3MT360X06F04S0 Y2, ±Ports 1920-2200MHz





2C2U3MT360X06F06S0 Y1, ±Ports 1920-2200MHz





2C2U3MT360X06F06S0 Y2, ±Ports 1920-2200MHz





2C2U3MT360X06F00S0 Y1, ±Ports 2300-2700MHz





2C2U3MT360X06F00S0 Y2, ±Ports 2300-2700MHz





2C2U3MT360X06F02S0 Y1, ±Ports 2300-2700MHz





2C2U3MT360X06F02S0 Y2, ±Ports 2300-2700MHz





2C2U3MT360X06F04S0 Y1, ±Ports 2300-2700MHz





2C2U3MT360X06F04S0 Y2, ±Ports 2300-2700MHz





2C2U3MT360X06F06S0 Y1, ±Ports 2300-2700MHz





2C2U3MT360X06F06S0 Y2, ±Ports 2300-2700MHz



2C2U3MT360X06F00S0 Y3, ±Ports 3550-3700MHz



2C2U3MT360X06F00S0 Y4, ±Ports 3550-3700MHz



2C2U3MT360X06F00S0 V1, ±Ports 5150-5925MHz

